TEST REPORT

Report No.

: 11-12-EAT-150-E00

Applicant

: SUNNY PROCESS CO., LTD

Address

: No. 109, Sec. 3, Fuxing Rd., Xinzhuang Dist.,

New Taipei City 24251, Taiwan

Commodity

: STONONLEAD

Model

: LB-B,LB-L

Quantity

: 2 pcs

Date of Receipt

: Dec. 29, 2011

Testing Item

:Insulation resistance test

Testing Laboratory Name: Electronics Testing Center, Taiwan - EMC/Safety/Reliability

Testing Laboratory

Address

: No. 8, Lane 29, Wenming Rd., Guishan Shiang,

Taoyuan County, Taiwan 33383

: No. 64, Wenming Rd., Guishan Shiang, Taoyuan

County, Taiwan 33383(Optical test) TEL:03-3280026 FAX:03-3276127

http://www.etc.org.tw

(Signature)

Tested by : Lii jin Zrong

Approved by : _> (Signature)

Sophia Liu

Contents: Total 4 pages

Note: 1. The results of the testing report relate only to the items tested.

2. The testing report shall not be reproduced except in full, without the written approval of ETC.

Report No.: <u>11-12-EAT-150-E00</u>

Testing Conditions: According to applicant's specifications.

Insulation resistance test

Sample model: LB-B, LB-L (As shown in figure 1~2)

Test voltage: 10V_{dc}

Duration: 1 minute

Measure position: Piont to piont (As shown in figure 3~4)




Fig.1: Model: LB-B




Fig.2: Model: LB-L



Fig.3: Insulation resistance test

Model : LB-B




Fig.4: Insulation resistance test

Model: LB-L



Report No.: <u>11-12-EAT-150-E00</u>

Testing Equipment:

Name	Model	Cal. Date	Due. Date
High Resistance Meter	HP 4339B	Dec. 12, 2011	Dec. 11, 2012

~END~





Report No.: <u>11-12-EAT-150-E00</u>

Testing Result:

Insulation resistance test

Date of testing: Dec. 29, 2011

Model	Insulation resistance (Ω)	
LB-B3	1.9873×10 ⁶	
LB-L2	2.2439×10 ⁶	

~END OF REPORT~

